

Fall of Ground and Falling/Sliding Material (7)

- operating single boom jumbo drill when a massive roof fall occurred and collapsed canopy
- hand scaling hanging wall when a slab of rock fell
- operating air-track drill when ground fell from pillar
- 50 foot high wall face fell on excavator while clearing rock and overburden near the high wall face
- truck driver got between tailgate of truck and steepened stockpile just before the stockpile sougled
- unsecured hopper barrier wall fell on victim while moving crusher
- ledgeman hit by 17,000 lb. slab of granite

Preliminary 1/6/98